










staal / steel

pos.	artikel nr. part no.	aantal quantity	frame deel frame part	maat mm. size mm.	ø mm.	pos.	artikel nr. part no.	aantal quantity	frame deel frame part	maat mm. size mm.	ø mm.
1	38061-PG	1		A 970+30 B 1000 W 215	25x1 22x1 25x1	7	38390	3		260	22x1
2	38062-PG	1		A 970+30 B 1000 W 215	25x1 22x1 25x1	8	38292	2		540+60	25x1
3	38060-PG	1		C 570+30 D 185+30 W 215	25x1 25x1 25x1	9	38421	2		840+60	25x1
4	35455	5		1100	22x1	10	36660	2		1100	22x1
5	38285-PG	10		940+60	25x1	11	38297	4		740+60	22x1
6	38379	5		1100	22x1	12	35988	2		1100	19x1
						13	34069	2		600	25x1
						14	38304	3		940+60	25x1
						15	38707	2		1100	25x1

Access.	Aantal / Qty.
B = buisklem / adjusting clamp 25 mm.	15
C = tentoog / plastic eye	5
schroef / screw	10

BEWAAR DEZE FRAME TEKENING
KEEP THIS FRAME DIAGRAM IN A SAFE PLACE
Voor nalevering van losse framedelen altijd het
framenummer en het artikelnummer opgeven.
When ordering separate frame parts always mention
the diagram number and part number.

Rev. V2