














staal / steel

pos.	artikel nr. part no.	aantal quantity	frame deel frame part	maat mm. size mm.	∅ mm.	pos.	artikel nr. part no.	aantal quantity	frame deel frame part	maat mm. size mm.	∅ mm.
1	38103-PG	1		A 1000 B 1000 C 570+30	25x1 22x1 25x1	6	36660	3		1100	22x1
2	38104-PG	1		B 1000 C 570+30 D 1000	22x1 25x1 25x1	7	38421	2		840+60	25x1
3	38100	1		C 570+30 E 215 F 600	25x1 25x1 25x1	8	34069	4		600	25x1
4	35455	7		1100	22x1	9	39864-PG	4		800	25x1
5	38285-PG	12		940+60	25x1	10	34026	4		600	22x1
						11	38423	2		1100	22x1
						12	38312	2		800	25x1
						13	38292	4		540+60	25x1

Access.	Aantal / Qty.
B = buisklem / adjusting clamp 25 mm	18

BEWAAR DEZE FRAMETEKENING
KEEP THIS FRAME DIAGRAM IN A SAFE PLACE
Voor nalevering van losse framedelen altijd het
framenummer en het artikelnummer opgeven.
When ordering separate frame parts always mention
the diagram number and part number.