



steel

pos.	part no.	quantity	frame part	size mm.	ø mm.	pos.	part no.	quantity	frame part	size mm.	ø mm.
1	41398	1		215	25x1	5	35455	4		1100	22x1
2	41397	1		215	25x1	6	39362	1		600+940	22x1
3	39467-PG	1		A 870+30 B 940+60 C 670+60 W 100/100	25x1 25x1 25x1 25x1	7	35988	1		1100	19x1
						8	39223-PG	2		840+60	25x1
4	39468-PG	1		A 870+30 B 940+60 C 670+60 W 100/100	25x1 25x1 25x1 25x1	9	38322	2		600	22x1
						10	38285-PG	2		940+60	25x1
						11	39222-PG	3		940+540+60	25x1
						12	38355	3		1100	22x1
						13	37838	2		290	22x1

Access.	Aantal / Qty.
B = buisklem / adjusting clamp 25 mm.	11

BEWAAR DEZE FRAMETEKENING
KEEP THIS FRAME DIAGRAM IN A SAFE PLACE
Voor nalevering van losse framedelen altijd het framenummer en het artikelnummer opgeven.
When ordering separate frame parts always mention the diagram number and part number.